



cmcpro.com
6740 Cortona Dr.
Goleta, CA 93117
800-235-5741
805-562-9120

PRODUCT SAFETY NOTICE

November 22, 2022

ATOM™ CHEST HARNESS

Part# 202363

CMC has become aware of a manufacturing issue in the ATOM Chest Harness (CMC Part # 202363) during regularly scheduled quality testing. There have been no inquiries or incidents reported by users in the field, and there is no known risk to user safety. We have corrected this issue for current and future ATOM Chest Harness production.

Lot numbers affected: 037509, 039421, 039568, 039734, 040908, 041293, 043094, 045182, 048253, 049982, 050392, 051665, 052026, 052027, 052571

Resolution: We request that you remove your ATOM Chest Harness from service and disable it so that it cannot be returned to service. We will send replacements free of charge upon receipt of the following:

- Remove the Dorsal D-ring from your unit by cutting the web loops.
- Take a picture of the unit with the D-ring removed.
- Take a picture of the printed label identifying the lot number.
- Email your pictures and shipping address to info@cmcpro.com.



This notice refers only to the separate ATOM Chest Harness. ATOM full body harnesses are not affected. If you have any questions, please contact our Customer Support team by calling 800-513-7455, or emailing info@cmcpro.com. Thank you for your continued support and trust!